


# Structurally Deficient Bridges on the National Highway System

## 51st Congressional District of California, 2003



| Structure Number | Road           | Location          |
|------------------|----------------|-------------------|
| 1 57 0318        | ROUTE 94       | 11-SD-094-6.16-SD |
| 2 57 0542R       | INTERSTATE 8   | 11-SD-008-R73.96  |
| 3 58 0113R       | STATE ROUTE 86 | 11-IMP-086-45.68  |

### Legend

Structurally Deficient Bridges
 Interstate Highways
 California District 51

Cities
 State Highways
 Urbanized Areas

Amtrak Routes
 Other Rail Lines
 Park Facilities

Airports
 Navigable Waterways
 Military Bases

Amtrak Stations



U.S. Department of Transportation  
Bureau of Transportation Statistics  
Federal Highway Administration

The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's 2001 National Bridge Inventory. Of the 6,643 structurally deficient bridges nationwide, 416 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive safety inspections every two years. The bridges listed were categorized as structurally deficient at the time the maps were developed.